

Document Log Item

Addressing	
From	To
"Jim Cox" <jcox@cosintl.com>	Carl Goldstein/R9/USEPA/US@EPA <pjp617@uow.edu.au>
CC	BCC
"SAM Willem Martins" <wmartins@sampac.com> "SAM Ken Mcleod" <kmcleod@sampac.com>	
Description Form Used: Memo	
Subject	Date/Time
High Strength Tank Leak	08/23/2007 08:29 PM
# of Attachments	Total Bytes
8	1,310,484
NPM	Contributor
	Marcela VonVacano
Processing	
Comments	

Body

Document Body

I have attached a write-up giving an account of the incident and also attached some pictures of the normal tank bottom, repair area, and the pipe return from catchment sump to line to HS tank.



- SampacJune2007 095.JPG - SampacJune2007 088.jpg - SampacJune2007 089.JPG - SampacJune2007 090.JPG - SampacJune2007 091.JPG - S